

Part -I

Performa for the Safety School Building  
(To be filled by the Head of School/Institute)

- |                                     |   |  |  |
|-------------------------------------|---|--|--|
| 1                                   | Name of the School  | TAGORE GLOBAL SCHOOL                           |  |
| 2                                   | Location  | VILLAGE DYALLPURA,<br>LUDHIANA CHANDIGARH ROAD |  |
| 3                                   | Plot Area   | THREE ACRES TWO KANALS(13000 SQ.MTR.)          |  |
| 4                                   | Plinth Area   | 34080 SQ FEET                                  |  |
| 5                                   | Number of Storey  | GROUND + THREE                                 |  |
| 6                                   | Year of construction of building  | 2015   |  |
| 7                                   | Supervision of the qualified Engineer   |  |  |
| The following details may be given: |   |  |  |
|                                     | a) Name of the Engineer   | MR.MANINDER SINGH                              |  |
|                                     | b) Address  | PUNJAB MATA NAGAR LUDHIANA                     |  |
|                                     | c) Set of structure Drawing used in the construction if available                                     | THREE NO'S                                     |  |
|                                     | d) Name of Architect  | MR.MANINDER SINGH                              |  |
| 8                                   | Whether the building has been constructed for the purpose of :  |  |  |
|                                     | a) School   | (Yes/No) YES                                   |  |
|                                     | b) Residential purpose and covered for use as a school  | (Yes/No) YES                                   |  |
| 9                                   | Material used for roof  |  |  |
|                                     | a) RCC Slab   | (Yes/No) YES                                   |  |
|                                     | b) RS Joists and Battens  | (Yes/No) .....                                 |  |
|                                     | c) Wooden joist and Battens   | (Yes/No) .....                                 |  |
| 10                                  | Material used for walls   |  |  |
|                                     | a) Mud Motor  | (Yes/No) .....                                 |  |
|                                     | b) Cement Motor   | (Yes/No) YES                                   |  |
|                                     | c) Plaster i) Lime Motor  | (Yes/No) .....                                 |  |
|                                     | ii) Cement Motor  | (Yes/No) YES                                   |  |
| 11.                                 | Flooring  |  |  |
|                                     | a) Conglomerate   | (Yes/No) .....                                 |  |
|                                     | b) Terazzo  | (Yes/No) YES                                   |  |
|                                     | c) Brick Paving   | (Yes/No) .....                                 |  |
| 12.                                 | Detailed Drawing Indicating dimensions of the rooms along with size and location of doors and windows |  |  |

For Tagore Global School

President Secretary Cashier  
Signature with Stamp of

The Head of the School/Institute



Part-II

(To be filled by S.D.E. of P.W.D. B & R Department)

I have visited the above mentioned school on 02/05/2025 and have visually inspected it from all angles of safety and I found it fit for normal use as School building.

In case any addition/alteration of expansion and modification of this building is to be carried out the same be carried out under the supervision of a technically specified Engineer and this certificate may again be obtained after the completion of work from the undersigned.


In case of building is affected by flood or if there is settlement of walls /foundations or caves of roof etc immediately inspection of the undersigned be arranged to check the stability and safety of the building.

The area as written in the application form has been verified and found correct as per site.

The fee submitted is correct as per building up area of school and Govt. notification for fees.

The fee deposited by the school has been verified on portal.

This building can be safely occupied for normal use up to 31/03/2026 (indicate year up to which it can be used) 31/03/2026

  
Sub Divisional Engineer,  
P.W.D. B & R Branch, Ludhiana

  
JE